# DeviceXPlorer OPC Server OPC UA Certification

■ How to create application certification

The procedure which makes an application certificate is indicated in the following.

### (1) Launch OPC UA Configuration Tool.

UA Configuration Tool

(2) Add DeviceXPlorer.exe item from Manage Application tab. (Click "Find" button.)

(3) Select application configuration file (DeviceXPlorer.Config.xml) from Browse button.

(4) Create application certificate.

■ How to specify trust list

The procedure as which the certificate store DeviceXPlorer trusts is indicated in the following.

(1) Select trust list of DeviceXPlorer from "Assign Certificate Trust List "button.

DeviceXPlorer OPC Server OPC UA Certification

■ Note on using HTTP protocol

When configuration file includes HTTP URL in "BaseAddresses" of "ServerConfiguration "item, DeviceXPlorer launch self-host web server.

For register URL to Windows OS, you have to run "DeviceXPlorer" by "Administrator" right.
If you don't run DeviceXPlorer by "Administrator" right, following error message will be shown.